

12/20/17  
TT: 3687.59

#3

# AIRCRAFT MAINTENANCE RECORDS



**N** 8792N

# PROP LOG BOOK



# AIRCRAFT MAINTENANCE RECORD

Page No. \_\_\_\_\_

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
<b>CARRIED FORWARD</b> →		
6/4/2019		Piper PA28-140 SN 28-25833 Sensenich 74DM6 SN K-28105 Hangar 64 <b>N8792N</b> Tach: 3959.36 Hobbs: 0639.2 4 June 2019 Propeller
		Propeller inspected IAW 14 CFR Part 43, Appendix D, using Piper & Sensenich data as a guide. AD compliance checked using ATP Hub, Revision 06/01/2019. AD list provided to owner. AD 66-23-02 PCW - blades do not have decals. Propeller leading edges dressed to remove light corrosion & pitting. I certify that this propeller has been inspected IAW with a 100 Hour inspection and determined to be in an airworthy condition.  John V. White, A&P #3035433 IA
6/2/17/2020		Piper PA28-140 SN 28-25833 Sensenich 74DM6 SN K-28105 Hangar 64 <b>N8792N</b> Tach: 4029.47 Hobbs: 0722.0 17 February 2020 Propeller
		Propeller inspected IAW 14 CFR Part 43, Appendix D, using Piper & Sensenich data as a guide. AD compliance checked using ATP Hub, Revision 02/15/2020. AD list provided to owner. AD 66-23-02 PCW - blades do not have water soluble decals. I certify that this propeller has been inspected IAW with a 100 Hour inspection and determined to be in an airworthy condition.  John V. White, A&P #3035433 IA


**SUB-TOTAL** THIS PAGE

**TOTAL** - CARRY FORWARD TO NEXT PAGE